

Energy Performance Certificate


Scotland

Non-Domestic buildings and buildings other than dwellings

NOBLE DRILLING UK LTD, WELLHEADS ROAD, ABERDEEN, AB21 7HG

Date of assessment:	19 Feb 2019	Reference number:	4110-0531-1439-2492-6006
Date of certificate:	03 Mar 2019	Building type:	Office/Workshop
Total conditioned area:	2180.5 m ²	Assessment software:	EPCgen, v5.4.b.0
Primary energy indicator:	540 kWh/m ² .yr	Approved organisation:	Sterling Accreditation Ltd

Building Energy Performance Rating



Approximate Energy Use: 230 kWh per m² per year
Approximate Carbon Dioxide Emissions: 92.22 kgCO₂ per m² per year

The building energy performance rating is a measure of the effect of a building on the environment in terms of carbon dioxide (CO₂) emissions. The better the rating, the less impact on the environment. The current rating is based upon an assessor's survey of the building. The potential rating shows the effect of undertaking all of the recommended measures listed below. The Recommendations Report which accompanies this certificate explains how this rating is calculated and gives further information on the performance of this building and how to improve it.

Benchmark

A building of this type built to current building regulations at the date of issue of this certificate would have a building energy performance rating of: 25 B

Recommendations for the cost-effective improvement of energy performance

1. Replace 38mm diameter (T12) fluorescent tubes on failure with 26mm (T8) tubes.
2. Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.
3. Consider replacing T8 lamps with retrofit T5 conversion kit.
4. In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows.

There are additional improvement measures applicable to this building. Refer to the Recommendations Report.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE BUILDING AND NOT BE REMOVED UNLESS REPLACED WITH AN UPDATED CERTIFICATE.